May 10, 1988

Michael J. Thomas Environmental Coordinator LTV Steel Company 11600 So. Burley Avenue Chicago, IL 60617 312/933-4522 or 219/391-2840

Angela Aye Tin, Manager
Technical Compliance Unit
Compliance Section
Illinois Environmental Protection AGency
Division of Land Pollution Control
2200 Churchill Road
Post Office Box 19276
Springfield, Illinois 62794-9276

EPA Region 5 Records Ctr.

307748

Re: 0316500002 - Cook County LTV Steel Company ILD 056623598 Compliance File

Dear Ms. Tin:

In reply to the subject Compliance Inquiry letter the following corrective action has been taken to resolve the apparent violations identified in your attachment "A".

A revised training plan has been written and implemented.

A copy of the plan is attached. This plan includes job titles of position's related to hazardous waste management, job descriptions, a description of the training to be conducted and a form for recording the required training. These records are maintained at our facility.

continued.....

RECEIVED MAY 1 3 1988 IEPA-DLPC

Re: 031650002 - Cook County LTV Steel Company ILD 056623598 Compliance File PAGE 2 of 2

Your reference to apparent violations found in previous inspections being found again does not seem to be supported by the inspection report we received. No apparent violations were specified during the previous inspection regarding training.

If you have any further questions, please contact the writer.

Very truly yours,

LTV STEEL COMPANY

Michael J. Thomas

Environmental Coordinator

Chicago Works

MJT:mz

cc: R. Finley

IEPA Maywood, IL

encl.

bcc: C. Broman

T.A. Dockus

B.R. Norris

L.A. Szuhay

file

5/9/88

LTV STEEL COMPANY

SOUTH CHICAGO WORKS

RESOURCE CONSERVATION AND RECOVERY ACT PERSONNEL TRAINING PLAN

265, 16

Introduction

All personnel whose normal duties involve the handling of the hazardous wastes generated at the South Chicago Works will be trained in the following procedures within six months of assignment and annually thereafter. This program will be executed under the direction of the Safety Coordinator and the Superintendent of Environmental Control.

Conduct of Training

Safety/Environmental Control will conduct training of all General Supervisors whose responsibility includes facilities that generate hazardous waste, and those positions who have responsibilities defined in the RCRA Contingency Plan. Those positions include the following:

Superintendent, Environmental Control Dept.

Works Safety Coordinator

Environmental Engineers

Environmental Engineer Bar Division

Supervisor Water Treatment

Supervisor Wire Mill Cleaning House

General Foreman By-Products

Supervisor AKJ Process

The above personnel are responsible for conducting the training for their subordinate personnel and where applicable including appropriate procedures in departmental Job Safety Analysis (J.S.A.'s).

Content of Training (Training Outline Attached)

- 1. Identification of hazardous waste.
- 2. Hazards involved.
- 3. Protective clothing or equipment required.
- 4. Hazardous Waste Manifest requirements.
- 5. Responsibilities in the event of a release, fire, explosion or incident as stated in the RCRA Contingency Plan.

Training Records

A chronological record of training will be maintained by the individual conducting the training. This record must include; individual trained, job, title, and date of training. The attached form may be used in conjunction with the individuals Safety Control Card.

Distribution

A copy of the RCRA Personnel Training Plan will be distributed to the following individuals:

Superintendent, Environmental Control

Manager, Maintenance & Services

Manager, 11" Bar Mill

Manager, Coke Plant

Environmental Engineers

Environmental Engineer Bar Division

Distribution (cont'd)

Supervisor Water Treatment
Supervisor Wire Mill Cleaning House
General Foreman By-Products
Supervisor AKJ Process
Works Safety Coordinator
Corporate Manager Solid Waste

MJT: mz

RCRA PERSONNEL TRAINING RECORD

Job Title:		
Employee Name:		
Job Description:		
· · · · · · · · · · · · · · · · · · ·		
Description of Training:		
a. Identification of ha	ızardous wastes.	
b. Hazards involved.		
c. Protective clothing	or equipment requi	ired
_		
d. Hazardous Waste Mani	-	
e. Responsibilities in		
explosion or inciden	it as stated in the	e RCRA Contingenc
Plan.		
Log of Training:		
Type of Training	Date	Signature
		

Training Outline

- 1. Identification of Hazardous Wastes
 - a. Characteristics of Hazardous Wastes
 - b. Hazardous Waste from non-specific sources
 - c. Basis for listing hazardous wastes
 - d. Hazardous Waste from specific sources
- 2. South Chicago Works Hazardous Wastes

Mill Area	DOT Shipping Name	Waste Number
Wire Mill Cleaning House	RQ Waste Sulphuric Acid, Spent, Corrosive ORM-E UN1832	K062 F2
Plant General	RQ Waste Petroleum Naphtha Combustible Liquid UN1255	D001 K
Coke Plant By-Products	Decanter Tar Sludge	K087 E

- 3. Individual protective measures for personnel working with hazardous wastes will be defined in departmental Job Safety Analysis
 - (J.S.A.'s) and can include the following:
 - a. Personal hygiene requirements
 - b. Face shields
 - c. Rubber boots, gloves and aprons
- 4. Hazardous Waste Manifest Requirements.
- 5. RCRA Contingency Plan.